ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
1

Ward Name
Kempegowda Ward

Street ID
W0138, W0132, W0145, W0126, W0141, W0143, W0077, W

Street Name
2nd Crs, NA, 14th Crs, 13th Crs

Significant Landmark
MVS Bakery road, Bhuvan Collage road

Segment No.
1/C-W0138/S104736

Total Length (m)
891.89

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	239.86	77.602474	13.111930	77.604641	13.111559	RI-A17	W0127
2	255.18	77.605212	13.111684	77.607556	13.111486	RI-A17	W0517
3	135.92	77.606172	13.111355	77.607417	13.111209	W0138	W0517
4	260.93	77.604890	13.111219	77.607272	13.110906	RI-A17	W0517

Work Details

History of Road / Lane / Circles

Name of the Work
Asphalting and Improvements to Roads at MVS Bakery road, Bhuvan Collage road & surrounding areas in Ward no 01 of Yelahanka Sub-Division Yelahanka zon

Sanctioned Estimated Amount (Rs.)
7500000

Sanctioned Year
2017

Year
2017 - 2018

Type of Work
Asphalting

Other Work Type

Tender
Not a Tender

Work Details
Asphalting and Improvements to Roads at MVS Bakery road, Bhuvan Collage road & surrounding areas in Ward no 01 of Yelahanka Sub-Division Yelahanka zone

Job No. / Work Code
001-17-000061

Work Order No.
BBMP/EE (YNK D)/WO/88/2017-18

Work Order Date
30/06/2017

Period of Extention
90 DAYS

Defect Liability Period From
30/07/2017

Defect Liability Period To
29/07/2018

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)

KRIDL

Phone No.	E-Mail ID	0.00
9449863065		

Field Inspection Details

Number of Trees	Any Other Information	Name
6		SACHIN
Date of Inspection	**Remarks**	
07/08/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0138, W0132, W0145, W0126,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	07/08/2017	06/09/2017	COMPLETED
SE	VASU K M	07/08/2017	06/09/2017	COMPLETED
EE	VASU K M	07/08/2017	06/09/2017	COMPLETED
AEE	DEVARAJ	07/08/2017	06/09/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0138, W0132, W0145, W0126,